

Installation of PondTec Ultrasonic Units, Kent, June 2011



This new building is surrounded on three sides by a moat and having tried numerous methods unsuccessfully to eliminate the unattractive algae, the management decided to use ultrasound. In June 2011, two PondTec ultrasonic units were installed by Sustainable Soil & Water Ltd.





One of the two PondTec 50 units in position





The second PondTec 50 unit





©www.emsustains.co.uk

Views of the moat, showing the algae problem



©www.emsustains.co.uk



©www.emsustains.co.uk

July 2011 and three weeks after the units were installed, all the algae has been eliminated.



©www.emsustains.co.uk



©www.emsustains.co.uk

The moat now looks much more attractive



©www.emsustains.co.uk



All the algae has gone and the base of the moat is now clearly visible





©www.emsustains.co.uk

The fish in the moat can now be seen.



©www.emsustains.co.uk

Sustainable Soil & Water Ltd

Lofthouse, May Lane, Claughton on Brock,
Garstang, Lancashire. PE3 0PE
Tel: 07860 447745 E: simon@emsustains.co.uk

www.ultrasonicalgaecontrol.co.uk

or

www.emsustains.co.uk

UK Distributor of PondTec Ultrasonic devices for

